Warwickshire CC Pre-Adopted Inspection Failure Codes

Δ.	4 Unit number is missing
A	1 Unit number is missing
Unit no. on site	2 Unit number should be black with white background graphic sticker—street lights
	3 Unit number should be black with yellow background graphic sticker – signs
	4 Unit number incorrect
ı sit	5 Unit number should be positioned 3m from ground level on the same orientation as the lantern
Ö	6 Unit number is faded or damaged and should be replaced for new
В	1 Planting depth is too low from manufactures specification (tolerance +/- 50mm)
Position & Depth	2 Planting depth is too high from manufacturer specification (tolerance +/- 50mm)
	3 Reinstatement – tarmac not neatly cut and/or laid
	4 Reinstatement – verge is uneven and/or not seeded with grass seed
	5 The unit is not planted on Highway land
	6 Column door should face towards on-coming traffic
	7 Column is not in the correct position according to the As-build drawing
	8 Requires tree-trim to clear foliage from under the lantern
	9 Requires tree-trim to clear foliage obstructing door access
	10 Unit does not have vehicular access for a MEWP to maintain it
	11 Access or bollard keys will be required for maintenance
	12 Access Issue - see notes
	13 Column planted in verge does not have concrete hard surface plinth/watershed
	14 Column plinth/watershed area is not to 1m x 1m specification
С	1 Lantern specification is incorrect according to As-built drawing
Lantern	2 Lantern is the wrong colour
	3 Lantern is not straight – should be 90 degrees to the road
	4 Lantern bowl is not clean
	5 Lantern is not working
	6 Lantern is day burning - please rectify the fault
	7 Lantern is damaged and needs replacing
	8 Incorrect wiring has been used, should be 2.5mm Core arctic Flex (outer sheath blue)
	incorrect wiring has been used, should be 2.5iiiii Core arctic riex (outer sheath blue)
C	1 Column is nainted (D) (Mallatite (MA) coated in the wrong colour
Painting	1 Column is painted (P)/Mallatite (M) coated in the wrong colour
	There is paint (P)/Mallatite (M) damage on the door
	There is paint (P)/Mallatite (M) damage at the base
	4 There is paint (P)/Mallatite (M) damage on the swage
	5 There is paint (P)/Mallatite (M) damage on the column shaft
	6 There is paint (P)/Mallatite (M) damage on the bracket
	7 The bracket is the wrong colour
	8 There is Mallatite damage over the whole column. Entire column requires replacing
_	
E	1 Door is not greased
	2 The column is not plum or upright
	The unit should be Passive Safe
	The unit should be Raise and Lower
	5 The column should be Heavy duty to take banners/hanging baskets/Xmas decs
	6 The unit is the wrong height
6	7 The bracket is not as designed

dum m	8 The bracket is damaged
5	9 The bracket is not secure or aligned correctly
	10 The column is loose in the ground
	11 The column is damaged and/or not structurally sound. New column required.
	12 The column door is damaged and requires replacing
	13 The column door is damaged and needs repairing
	14 Safety bolt missing in Raise & Lower column
F	1 Earth tag is missing
	2 Earth tag is incorrectly installed
	3 Earth to door needs removing
	4 Chain on door needs removing
	5 There should be two clips on the backboard securing cables to lantern
_	6 The backboard is not secure
Internal/Electrical	7 The cut out is not securely attached to the backboard
rna	8 The cut out is damaged and needs replacing
ıl/E	9 The cables are not double insulated going in to the cut out
lect	10 Cables need to be tidy and terminals tight
rica	11 Feed identification labels are missing
=	12 Schematic drawings are missing – required in feeder pillars
	13 The unit is not serviced - Contact your DNO
	14 The unit is not working - Dead Service - Contact your DNO
	15 Disconnected Unidentified/Redundant cable in base
	16 Earth bolt rusted and needs replacing
	, ,
G	1 The unit does not have an electrical test certificate
Т	2 The electrical test certificate is incorrect
SOL	3 The electrical test certificate is out of date
Н	1 Telensa node is not fitted
	2 Telensa unique number has not been supplied
Tel	3 Telensa sticker is not shown inside of column
Telensa	4 Telensa sticker in column is not the reference number on the Telensa node
ត្	5 Base-station is in the wrong location
1	1 The wrong sign face is attached
	2 The sign face is the wrong size
	3 The sign face doesn't have Neoprene strips under the torques to protect the column
Attachments	4 The sign face is damaged or faded and needs replacing
achı	5 The sign face is not straight
mei	6 The sign is mounted too low - signs should be a minimum of 2.1m high
nts	7 The sign is too large for the column height
	8 Sign plate missing - no sign plate attached